

1A

Rm < 450 N/mm²





Micro Z=2


ACIER

STAHL

STEEL



Z=2: Vf
Z=3: Vf*1.4
Z=4: Vf*1.7



1C

$700 < R_m < 900 \text{ N/mm}^2$





Micro Z=2

ACIER

STAHL

STEEL



Z=2: Vf
Z=3: Vf*1.4
Z=4: Vf*1.7

